

ASOS ERRATA SHEET 2 (for Electronics Technicians)

Engineering Division

W/OSO321:BGM

Replacement Page for ASOS Modification Note 12

GENERAL

This errata sheet provides instructions to correct ASOS Modification Note 12. The reason for the change is to correct parameters located on page A-5, item D, DISABLE "AT" COMMANDS, lines 42 and 44. Line 42 was changed from NO to YES. Line 43 was moved and renumbered as line 44 and the NO was changed to YES. The original line 44 was renumbered as line 43.

A corrected page A-5 is provided with this errata sheet. The areas where corrections were made are highlighted.

PROCEDURE

1. Remove page A-5 of ASOS Modification Note 12 and replace with corrected page attached to this errata sheet.

EFFECT ON OTHER INSTRUCTIONS

Replaces errata sheet 1, page A-5 of EHB-11, Section 3.6, ASOS Modification Note 12, issued March 17, 1994.

J. Michael St. Clair
Chief, Engineering Division

Attachment

W/OSO321:(BGM):AJWissman:rz:6/16/94:disk EHB 11-E,"errat12A-h11". spellchecked
corrected 6/22/94:WVF:rhz

	28.	CHANGE TO UNILATERAL CTS?	NO	
	29.	CHANGE TO RTS/CTS?	NO	
	30.	CHANGE TO DISABLED?	YES	
	31.	FLOW IS DISABLED, CHANGE?	NO	
	32.	XON/XOFF PASS THRU DISABLED CHANGE?		
TALK/DATA				
	33.	CHANGE MNP OPTIONS?		NO
	34.	CHANGE DTE OPTIONS	YES	
	35.	ASYNC DATA CHANGE TO SYNC?		NO
	36.	DTE RATE IS 9600, CHANGE?	NO	
	37.	8 BIT CHAR SIZE CHANGE TO 7?	NO	
	38.	NO PARITY CHANGE?		NO
	D. DISABLE "AT" COMMANDS			
	39.	"AT" COMMAND SET ENABLE, CHANGE?		YES
	40.	"AT" COMMAND SET DISABLE, CHANGE?		NO
	41.	IGNORES DTR CHANGE?	NO	
	42.	DSR FORCED HIGH CHANGE?	NO	
	43.	DCD FORCED HIGH CHANGE?	YES	
	44.	CHANGE TO DCD FROM REMOTE?		YES
	45.	DCD IS REMOTE CHANGE?		NO
	46.	CTS FORCED HIGH CHANGE?	YES	
	47.	CHANGE TO CTS FOLLOWS RTS?		NO
	48.	CHANGE TO CTS EQUALS RTS?	NO	
	49.	CHANGE TO CTS FOLLOWS DCD?		YES
	50.	CTS FOLLOWS DOD CHANGE?		
TALK/DATA				
	51.	CHANGE DTE OPTIONS?		TALK/DATA
	E. STORE PRESENT SETUP			
	52.	LOAD OR STORE OPTION SET?	YES	
	53.	LOAD FACTORY OPTION SET?	NO	
	54.	STORE PRESENT OPTIONS?		YES
	55.	ARE YOU SURE?	YES	
	56.	OPTIONS ARE NOW PERMANENT (displayed for 2 seconds, then)		
		MODIFY CONFIGURATION?		
TALK/DATA				
		V.32 9600/TRAINING		

NOTE: Display will read TRAINING until modems connect, then display will change to **ON LINE**.

18. On OID-2 (OID-3) change baud rate from 2400 to 9600. Press SET UP (F3). Move cursor using arrow keys to PORT. Move cursor down to PORT A SETTINGS. Press <ENTER>. Move cursor down to TRANSMIT BAUD RATE. Press <ENTER> until 9600 is selected. Press <SHIFT> <UP ARROW>. Move cursor to EXIT. Select EXIT AND SAVE CHANGES and press <ENTER>. Answer Yes to question. OID will be communicating with ACU.

(end of procedure)

W/OSO321:BGMcCormick:713-1834:6/15/94
WP51 Files: ERRAT12A.H11, EHB-11 disk 11a
Spellcheck sol 6/15/94